



# Step 1: Go to Device Manager



Step 2: Select the right COM Port

Step 3: Go to properties



Step 4: Go to Port Settings



Step 5: Go to Advanced...

Step 6: Pick the lowest available COM Port.

Step 7: Hit Ok, Exit Device Manager, and Restart Computer